

## Turcotte, Cheryl

---

**From:** David Wilson [David.Wilson@erm.com]  
**Sent:** Thursday, October 24, 2013 11:49 AM  
**To:** Turcotte, Cheryl  
**Cc:** Elaine Cawley (elaine@burlyseal.com); Jerry Faulconer (jerry@sealsandpackings.com); Steve Taylor (stevet@sealsandpackings.com); Lucy Jenkins (ljenkins@joneswaldo.com); Lonnie Mercer; Teri Peterson  
**Subject:** RE: Completion of PCB Remediation - Burly Seals Site (Tooele, Utah)

Hi Cheryl –

Thanks for your return call and VM message today. I am providing this follow-up correspondence to document both of our records, and to let Burly Seal know that EPA does not plan to revisit the site. Rather you will rely on the Final Remediation Report to document completion of the PCB remediation in accordance with the approved Cleanup Plan (as amended). Burly Seal may proceed with the concrete repairs at its convenience.

Much thanks,  
Dave

David S. Wilson, P.E., P.G.  
Partner  
Environmental Resources Management  
102 West 500 South, Suite 650  
Salt Lake City, Utah 84101-2334

Tel: +1 801 595 8400  
Mobile: +1 801 916 6957

[www.erm.com](http://www.erm.com)  
[david.wilson@erm.com](mailto:david.wilson@erm.com)

---

**From:** David Wilson  
**Sent:** Wednesday, October 23, 2013 9:38 AM  
**To:** Cheryl Turcotte ([turcotte.cheryl@epa.gov](mailto:turcotte.cheryl@epa.gov))  
**Cc:** Elaine Cawley ([elaine@burlyseal.com](mailto:elaine@burlyseal.com)); Jerry Faulconer ([jerry@sealsandpackings.com](mailto:jerry@sealsandpackings.com)); Steve Taylor ([stevet@sealsandpackings.com](mailto:stevet@sealsandpackings.com)); Lucy Jenkins ([ljenkins@joneswaldo.com](mailto:ljenkins@joneswaldo.com)); Lonnie Mercer; Teri Peterson  
**Subject:** Completion of PCB Remediation - Burly Seals Site (Tooele, Utah)

Hello Cheryl:

I am writing in follow up to the voice message I left for you this morning to report that the PCB remediation work at the Burly Seal facility in Tooele, Utah is complete. During the last three weeks, the final soil removal and concrete removal activities were completed and the PCB-affected materials have been loaded into roll-off containers for shipment to Clean Harbors' Grassy Mountain Facility. ERM will be preparing the Self-Implementing Completion Report pertaining to this work during the next month for submittal to EPA.

The only remaining activity is restoration of the concrete surfaces to satisfy the property owner. Burly Seal will be coordinating this activity with a local concrete contractor (with support from ERM), and a schedule for these repairs has not yet been established. However, we would like to confirm whether EPA intends to perform a final inspection of the

property and whether you plan to do this prior to repairs to the concrete surfaces. I anticipate that Burly Seal will want to complete the concrete work as soon as possible prior to winter weather conditions. Thank you for your reply.

Regards,  
Dave

David S. Wilson, P.E., P.G.  
Partner  
Environmental Resources Management  
102 West 500 South, Suite 650  
Salt Lake City, Utah 84101-2334

Tel: +1 801 595 8400  
Mobile: +1 801 916 6957

[www.erm.com](http://www.erm.com)  
[david.wilson@erm.com](mailto:david.wilson@erm.com)

---

This message contains information which may be confidential, proprietary, privileged, or otherwise protected by law from disclosure or use by a third party. If you have received this message in error, please contact us immediately at (303) 741-5050 and take the steps necessary to delete the message completely from your computer system. Thank you.

Please visit ERM's web site: <http://www.erm.com>